

# PACIFIC INT-R-TEK PIPELINE VIDEO REPORT

<b>Customer</b> City of Dayton		<b>Project</b> May 2017 San Clean TV Project		<b>Media Label</b> 10239	
<b>Location/Street</b> 6TH ST		<b>Surveyor</b> Kevin Odermann		<b>Report #</b>	
<b>Upstream ID</b> SSMH 12	<b>Downstream ID</b> SSMH 11	<b>Camera Direction</b> Downstream		<b>Date</b> 05-16-17	<b>Time</b> 7:41 AM
<b>Pipe Size</b> 8	<b>Pipe Type</b> PVC	<b>Sewer Use</b> Sanitary	<b>Purpose</b> Special	<b>Length TV'd</b> 217	
<b>Comments</b>					<b>Reference Ball</b> None

	Ftg.	Code	Description	Position	Severity	Comment
▼	0.0	MH	Manhole			SSMH 12
▼	11.4	TR	Transition (Pipe Change)			TRANS FROM PVC TO CP
	70.0	GR	Grease	11 to 1		START
	76.3	RM	Roots Mainline	11 to 1		FINE ROOTS
	101.6	G	Break in Grade (Sag)			CAM UNDER WATER
⋮						
▼	133.6	RM	Roots Mainline	11 to 1		FINE ROOTS
	134.0	GR	Grease	11 to 1		END
	135.5	G	Break in Grade (Sag)			CAM OUT FROM UNDER WATER
	176.2	G	Break in Grade (Sag)			CAM UNDER WATER
	196.8	G	Break in Grade (Sag)			CAM OUT FROM UNDER WATER
	215.0	LK	Leak	4 to 8		IT LOOKS LIKE GROUND WATER LEAKING IN @ THIS POINT
	215.0	BP	Broken Pipe	5 to 7		
	215.9	H	Hole	5		GROUND WATER
	217.0	MH	Manhole			SSMH 11