PACIFIC INT-R-TEK PIPELINE VIDEO REPORT

		stome of Day		May 201	Project May 2017 San Clean TV Project				Media Label 10239	
	Location/Street				Surveyor Kevin Odermann				Report #	
ALLEY				К					-	
	Upstream ID D SSMH 05			1		era Direction		Date 05-16-17	Time 1:53 PM	
	Pipe Size		Pipe Type		Sewer Use		Purpose		Length TV'd	
	8		CP	Sani			Special		220	
Comment	s							Refer	ence Ball	
									None	
	Ftg. ●0.0	Code MH	Description Manhole		Position	Severity	Comment SSMH 05			
+	•69.5	SR	Service Right		2					
	•86.4	SL	Service Left		10		GROUND V	VATER?		
	•92.4	SR	Service Right		2		0			
	•107.6	SR	Service Right		2		GROUND V	VATER		
₩ ▼										
	• 173.7 • 179.4	SL SR	Service Left Service Right		10 2		GROUND V GROUND V			
	• 183.0	SR	Service Right		2			ET AROUND T	HIS TAP	
	°217.7	LK	Leak				LEAKING G	GIDE DROP LO GROUND WATE	OKS LIKE IT IS ER	
	°220.0	MH	Manhole				SSMH 04			