

PACIFIC INT-R-TEK PIPELINE VIDEO REPORT

Customer City of Dayton		Project May 2017 San Clean TV Project		Media Label 10239	
Location/Street FERRY ST (HWY 155)		Surveyor Kevin Odermann		Report #	
Upstream ID SSMH 11	Downstream ID SSMH 10	Camera Direction Downstream	Date 05-16-17	Time 9:43 AM	
Pipe Size 8	Pipe Type CP	Sewer Use Sanitary	Purpose Special	Length TV'd 308	
Comments				Reference Ball None	

Ftg.	Code	Description	Position	Severity	Comment
0.0	MH	Manhole			SSMH 11
54.1	G	Break in Grade (Sag)			CAM UNDER WATER
72.4	G	Break in Grade (Sag)			CAM OUT FROM UNDER WATER
180.4	SL	Service Left	10		GROUND WATER
189.2	SR	Service Right	2		
192.0	G	Break in Grade (Sag)			CAM UNDER WATER
211.3	SR	Service Right	2		
224.9	G	Break in Grade (Sag)			CAM OUT FROM UNDER WATER
235.5	G	Break in Grade (Sag)			CAM UNDER WATER
256.5	G	Break in Grade (Sag)			CAM OUT FROM UNDER WATER
308.0	MH	Manhole			SSMH 10 (GROUND WATER IN THIS MH FROM THE WALL)